



◆ Wiring diagrams / 接線圖：

Single output / 單一輸出


N Output




N2 Output




P Output




P2 Output




ND/ND1/PD/PD1 Output



NB1/PB1 Output



NK/NK1/NM1/PK/PK1/PM1 Output




NPN/ PNP NO or NC 4-in-1 outputs


NP Output



NPB Output




NPK/NPK1 Output



KP2 Output



KP2K/KP2K1 Output



Fiber Sensor

Photo / Area Photo / Ultrasonic Sensor


Inductive / Capacitive Proximity Sensor

Others


◆ Wiring diagrams / 接線圖：

Linear analog output / 線性輸出

LA Output




LV Output




2-wires output / 二線式輸出

C Output




C2 Output




AC 90~260V


A Output



AK Output



A2 Output



A2K Output

